



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
KING ECGBERT ROAD	O/S 21	TR: Felling	Kerbs displaced and f/w uplifted by vigorous rooting	Prunus Kanzan	Plant in verge o/s 21 (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
KING ECGBERT ROAD	O/S 38 (opposite 37)	TR: Felling	Kerbs displaced and 3rd party wall damage	Prunus Kanzan	Plant in verge o/s 38 (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
KING ECGBERT ROAD	O/S 63	TR: Felling	F/W uplifted by lateral roots	Prunus Kanzan	Plant in verge o/s 63 (same position as felled tree)	Sorbus X Arnoldiana 'Schouten'
KING ECGBERT ROAD	O/S 49	TR: Felling	Stem wounded and parting at union	Prunus Kanzan	Plant in verge o/s 49 (same position as felled tree)	Sorbus X arnoldiana 'Schouten'
KING ECGBERT ROAD	O/S 57	senescent (TR: Felling)	50% crown dead	Prunus Kanzan	centrally in verge o/s 57	Malus or Prunus